







*W*

Rework necessary on both rear engine supports and drilling in frame "X" member that is necessary to adapt them for the 288 cu. in. engine