

No. 16

# Packard—Chicago

## Service Bulletin

Date 5-23-33.

*To:* ALL DEALERS AND BRANCHES

*Subject:* CORRECTION ON NUMBER 15 SERVICE BULLETIN  
REGARDING RELIEF OF VAPOR LOCK

Paragraph two is incorrect. Number sixty drill size hole should not go through the top dye casting but should go through the body of the tank itself about one half an inch to the right of the dye casting.

N. H. Peterson,  
General Manager of Service.

**Make every owner a salesman.**