



**Packard SERVICE TECHNICAL**

**Bulletin**

50T-3, Dealer 2  
February 1, 1950

To: ZONES AND DEALERS

Subject: DISCONTINUATION OF ULTRAMATIC DRIVE OIL CHANGE AT 1000  
MILE INSPECTION DURING WARRANTY PERIOD

Service Technical Bulletin 49T-33, Dealer 26, November 29, 1949 outlined the recommended procedure for inspecting and servicing the Ultramatic Drive within the warranty period.


The items listed under operation No. 2 of the bulletin call for cleaning and inspection operations and the replacement of the fluid at 500 miles or in connection with the 1000 mile inspection.

Due to additional cleaning operations and more concentrated inspection on units in production at the Factory, it is no longer considered necessary to follow that part of the bulletin pertaining to fluid change at the first 500 to 1000 mile period.

No R.F.A.'s will be accepted for payment of Ultramatic Drive fluid change on units from No. 5135 and No. 101908.

All other sections of service Technical Bulletin 49T-33 remain effective and should be followed.

Very truly yours,

  
J. A. Carr, Manager  
Parts and Service Department