

Packard SERVICE TECHNICAL Bulletin

51T-36

October 11, 1951

TO: ZONES

SUBJECT: CHANGES IN ULTRAMATIC (CONFIDENTIAL)


We are listing recent changes in the Ultramatic Drive unit. The part changed, the unit number on which the change was made and the date the change was made in production are shown.

The list is supplied simply as a matter of information for the use of Zone Parts & Service Managers and Representatives.

Any parts altered will not be shipped through Service until the previous design is exhausted.

<u>Unit No.</u>	<u>Name and Change</u>	<u>Part No.</u>	<u>Effective Date</u>
181154	Starter safety switch	423439	4-27-51
34916	Plug-in type terminals replace spade terminals		
183700	Control damper assembly	423452	5-15-51
37648	Improved type damper released to reduce valve noise.		
185865	Transmission case breather cover	423431	6-8-51
40145	Metal thickness increased to prevent dropping off after staking.		
188945	Clutch hub	421636	8-6-51
44380	Hub tooth clearance increased to help minimize burning of high range clutch plates		

Yours very truly,



J. A. Carr, Manager
Parts and Service Department

JAC:cml