

Packard **SERVICE TECHNICAL** **Bulletin**

53T-2
Dealer 2
January 20, 1953

TO: ZONES AND DEALERS

SUBJECT: CARBURETOR CHOKE SETTING CHANGED, "WCFB"
CARBURETOR, 26th Series

The choke setting on the "WCFB 985S" model carburetor has been changed to "on the index mark" instead of "1½ points rich." This new setting reduces the possibility of flooding the engine during cold starts.

Please make this change in your Service Counselors, Vol. 26, No. 11, November, 1952 "Mechanical Specifications and Adjustments", Vol. 27, No. 1, January, 1953, "WCFB Carburetor Model 985S".

Very truly yours,


J. A. Carr
General Service Manager

JAC:kb