

Packard **SERVICE TECHNICAL**
Bulletin

55T-41
Dealer 32
September 14, 1955

To: ZONES AND DEALERS

Subject: GASOLINE FUMES - MODELS 5560-80

Reports have been received as to gasoline fumes being present in the cars equipped with Rochester Carburetors, after very rapid deceleration or a fast right turn.


The correction should be as follows:

The carburetor must be removed by the dealer and sent to the nearest United Motors Service for corrective servicing. United Motors Service has received information from Rochester Products as to handling and corrective procedures.

Corrective work on the carburetor will be handled no charge by United Motors Service.

Attach the no charge invoice from United Motors Service to RFA to cover the removal and replacing of the carburetor by the dealer.

Very truly yours,



H. N. Johnson
Assistant Service Manager

TWN:mu