

TECHNICAL

55T-9 Dealer 8 February 3, 1955

To: ZONES AND DEALERS

Subject: FRONT UNDERSEAT HEATER FAN GUARD - 54TH SERIES

Several thousand early production 54th Series cars equipped with underseat heaters were shipped without fan guards.

We continue to receive reports of articles hitting the fan blades of the underseat fan causing noise, bending the blades and in some instances, the heater core is damaged. For these and other obvious reasons, it is important that fan guards be installed on all of these early production cars as quickly as possible.

The 1954 model cars coming into your dealership for service should be inspected for fan guard equipment and if required part number PA-458299, Guard Assembly, should be installed no charge to the owner.

An RFA should be submitted in the usual manner for the guard assembly and 0.3 hours labor allowance.

Part number PA-458299, Front Underseat Heater Fan Guard and Screen Assembly, is available from the Parts Warehouse.

Very truly yours,

Johnson

Assistant Service Manager

HGL:tf