



90-1001

D. S. McNALLY

Packard**SERVICE****TECHNICAL****Bulletin**

56T-11

February 17, 1956



To: ZONES

Subject: TRANSMISSION BAND ADJUSTMENTS

We have been advised that the information contained in Service Technical Bulletin 56T-6 is being considered servicing instructions such as the item "Brake Bands adjusted to 1 1/2 turns after transmission test."

The list of items in the bulletin is supplied as a matter of information and is so stated. It is a matter of record only, showing the unit serial number when changes went into effect.

The standard band adjustment is 1 3/4 turns off as described in your Service Manual. Any changes in servicing procedure will be covered in detail either by Service Counselor or Technical Bulletin.

Sincerely,

T. W. Nertney
Service Technical Manager

HGL:jb