

Packard-Chicago

Service Bulletin

Date 8-9-34

To: ALL DEALERS AND BRANCHES

Subject: IGNITION COIL INSULATION

Undoubtedly, you noticed the article in Volume 8, #15, of the August 1st Issue of the Packard Service Letter regarding the above subject.

We strongly recommend your campaigning all of the dual coils on your Tenth and Eleventh Series or on any of the earlier models on which you may have installed this equipment in order to eliminate the possibility of coil failure due to water getting in and around this binding post on the coils.

You may order out this bakelite cement from us in pint quantities. It is quite inexpensive and it should not take more than about ten minutes to service a pair of coils.

Yours very truly,

PACKARD MOTOR CAR COMPANY OF CHICAGO,



N. H. Peterson,
Service Manager.

NHP.MK.