

Packard—Chicago

Service Bulletin

No. 6

Date 12-28-32.

To: ALL DEALERS AND BRANCH SERVICE MANAGERS

Subject: HIGH TENSION IGNITION WIRE

Quite sometime ago, it was recommended by this office that the high tension ignition wire be removed from the conduit on your owners' cars. It will only take a few minutes to pull it out and the slack can be taken up underneath the dash by making a loop through a little rubber ferrule that is already in place.

We urge you to give this your attention as it will facilitate starting in cold weather and also will improve the performance of most cars, particularly if the insulation is broken down.

N. H. Peterson,
General Manager of Service.

Make every owner a salesman.