



Service Bulletin

SEPTEMBER 1958

NO. 341

SOUTH BEND 27, INDIANA

SERVICE BULLETIN INDEX - No. 311, April, 1956 through No. 339 July, 1958

This service Bulletin Index lists all the articles published in Studebaker-Packard Service Bulletins from Service Bulletin No. 331, April, 1956 through No. 339, July, 1958.

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
- A -				B - Cont'd.			
ADJUSTING ACTUATOR TO TRANSMISSION CONTROL valve detent - Push Button control	338	3	Ultramatic (Packard)	BORG PRODUCTS Division, Service Stations	333	6	
AIR CHAMBER BASE	323	1	57H-K & 57L	BRAKE INFORMATION	314	4	Ultramatic
AIR CONDITIONING KITS	324	6	57L-Y	Low Range	314	4	1956 Pass.
ANTENNAS, Servicing	330	4	1955-1956 & 1957 Packard	BRAKE PIPE & MUFFLER PIPE INTERFERENCE	336	2	All 1958 Sedans
ANTI-FREEZE in passenger cars & Trucks	324	4		BUMPER BAR DISTORTION	325	4	1957 Studebaker
ARM RESTS, Installation	319	2	1957 Models	BUMPER JACK, Usage	319	3	1957 Pass.
AUTOMATIC TRANSMISSIONS (Warner Gear)	313	3	2E7 & 2E12	- C -			
AUTO WASH STATIONS	333	4	1958 Pass. Models	CAMSHAFT & LIFTERS IN SHORT BLOCK ASSEMBLY	324	4	1951-1954 Studebaker H, 3H, 4H, & 5H
AUXILIARY-Fuel Pump Kit	339	3	Equipped with Super-charger	CAMSHAFT & LIFTER RE-PLACEMENT	321	4	1954 Comm.
- B -				CAMSHAFT TIMING GEAR	312	4	2E38 Trucks
BACKFIRING - 4BB1 carb. BAND ADJUSTMENT (Warner Gear)	316	2	56J	CAMSHAFT THRUST PLATE - 185 cu. in. Engines	328	4	Trucks & Passenger cars
Band Slippage & Erratic Shift Pattern	323	2	Flightomatic	CARBURETOR AIR CHAMBER BASE	331	1	1957 Golden Hawk & Packard Clipper
Battery Support Box	312	3	1956 Sedan & Station Wagon	CARBURETOR AIR CHAMBER - vent Valves noisy	319	5	Golden Hawk
BELT ADJUSTMENT with Air Conditioning & Power Steering	323	2	57L-Y	CARBURETOR GAUGE SETS	338	7	
BENDIX DISTRIBUTORS, for Carburetors & vacuum Power Items	324	2		CARBURETOR HIGH IDLE ADJUSTMENT	320	3	Golden Hawk 57H-K
BODY BOLT & front of Rear Spring interference	314	3		CARBURETOR ICING	333	5	Scotsman
BODY REAR GLASS MOULDINGS	312	2	1956-2 & 4 Door Sedan Models except Classic	CARBURETOR MODIFICATIONS	320	2	1957 Golden Hawk 57H-K & 57L Packard
				CARBURETOR (Stromberg), Revision	315	1	259 & 289 cu. in. engine
				CARBURETOR in Scotsman Models	326		
				CAR LEANING on Left Side	314	2	56B & 56H
				CARTER FOUR BARREL CARBURETOR CHANGES	333	2	58B 58H 58L

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
C - Cont'd.				D - Cont'd.			
CENTER ARM REST SCREW INTERFERENCE WITH PROPELLER SHAFT	335	7	58L-K9	DOOR LATCH REMOTE CONTROL BINDING	333	5	1958 Scotsman
CHECKING TWIN TRACTION DIFFERENTIAL	327	1	All Models	DOOR TRIM	317	1	1956 C & K
CLIMATIZER CONTROLS & HAND BRAKES, Clearance Between	319	1	1957 Sedans & Station Wagons	DOW CORNING 4 Silicone Compound for Body Noises & Squeaks	316	5	
CLIMATIZER KITS	321	4	1957 Packard Clipper	DUAL HEADLAMP, Rim Loose	333	5	1958 Studebaker Pass.
CLUTCH ASSEMBLY 8 1/2" DIA.	333	5	58G	- E -			
COAT HOOK INSTALLATION	335	2	1958 (W,F,Y) Sedan Models	ECON-O-MILER TAXICAB ELECTRIC ANTENNA	332	7	55th & 56th Series Packards
COLD ENGINE STARTING	337	5	Scotsman and Y1	ELECTRIC SHIFT ASSEMBLY- 2 Speed Rear Axle	333	6	
COMPOUND OF BODY NOISES & SQUEAKS	316	5		ELECTRIC SHIFT CONTROL (Timkin 2-speed axle)	313	4	
CONTROL ARM BUSHING RETAINERS	312	4	All Models	ENGINE CYLINDER & PISTON ASSEMBLY	331	6	1951-1954
CONTROL OIL PRESSURE - Automatic Transmission	331	7	3E & 2E Series Truck	ENGINE DETONATION	316	1	56J
CONTROL VALVE ASSEMBLY & GOVERNOR - Flightomatic	321	2	1957 Golden Hawk & Packard Clipper	ENGINE EXHAUST VALVE STEM DEFLECTORS	317	2	56B Comm. 56H Pres. Engines
CORRECTION TO SERVICE BULLETIN - May 1958	337		Trim Moulding 1958 Packard Hawk Models	ENGINE HOT, Hard Starting	325	2	1957 Golden Hawk & Packard Clipper
CORRECTION TO SUPPLEMENT CORRECTIONS OF WATER LEAKS AT REAR QUARTER CRANKSHAFT STARTING JAW	325	5	3E Series	ENGINE MISS OR SKIP	315	1	56J
	335	4	1958 J	ENGINE NOISES	314	1	56J
	313	3	2E Series Trucks	ENGINE NO. & IDENTIFICATION	317	2	56J
CRASH PADS	339	6	1957 L Packard	ENGINE OIL LOSS AT ROCKER ARM COVERS	328	1	1957 Studebaker & Packard V8 Engines
- D -				ENGINE OPERATING TEMPERATURE	327	1	1957 Golden Hawk & Packard Clipper Models
DIAGNOSIS AND PRESSURE CHECK INFORMATION	338	6	Packard Ultramatic (Prior to Gear Start Type)	ERRATIC ACTION of Torsion Level Suspension	325	5	55th & 56th Packard
DISTRIBUTOR CAP, Moisture in.	316	2	56J	ERRATIC SHIFT PATTERN & BAND SLIPPAGE	323	2	Flightomatic
DECK LID HINGES, Special	339	5	58G-Y1 Taxi-Cab	- F -			
DIRECT DRIVE CLUTCH ENGAGEMENT, Loss of	320	4	55th Series Packard	FAN BELT ADJUSTMENT - Alternating Current Generator	317	2	56B & 56H Police Cars, etc.
DISTORTION IN FRONT DOOR TRIM PANEL	337	3	1958 Scotsman D & F	FAN BLADE ASSEMBLY cracks & Breakage	316	2	56J
DISTRIBUTOR & SPARK MODIFIER ASSEMBLY	317	5	2E7, 2E13, & 2E28 Trucks	FIBERGLASS REPAIR KIT	335	1	Studebaker and Packard
DOME LAMP INSTALLATION	337	4	Scotsman W1, F1, and D1	FILLER PLUG INTERFERENCE with Ring Gear - Twin Traction Rear Axle	321	3	
DOOR BELT MOULDING	337	2	1958 J	FLIGHTOMATIC SERVICE PARTS	320	1	57H-K Golden Hawk & 57L Packard Clipper

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
F - Cont'd.				- H -			
FLIGHTOMATIC TRANSMISSION, Overheating Clutch & Band Failure	321	2		HARD SHIFTING INTO REVERSE GEAR	337	6	1958 Champion Models Equipped with T96 OD
FLIGHTOMATIC TRANSMISSION, Service Suggestions	328	2		HARD STARTING WITH HOT ENGINE	325	2	1957 Golden Hawk & Packard Clipper
FLOOR PAN COVER - Automatic Trans.	316	7	2E7 & 2E12	HAT TYPE DRY CARBURETOR AIR CLEANER	338	2	1958 Models with 488L Carburetor
FLUID TEMPERATURE AFFECTS ULTRAMATIC UPSHIFT	339	5		HEADLAMP RIM	336	3	All 1958 Models Except Hawk & Scotsman
FLYWHEEL SCREW	335	7	Packard Ultramatic	HEADLAMP RIM-TO-HOUSING SCREW - with Dual Headlamps	331	6	1958 Studebaker
FRAME 2nd CROSSMEMBER REINFORCEMENT	336	12	3E17, 3E28, 3E40 Trucks	HEAD LAMP RIVETS LOOSE	313	2	1956 Pass.
FRAME SUBSTITUTIONS	335	6	1955-1956 Studebaker	HEADLINING FLUTTER	337	1	1958 Hawk
FRONT END NOISE	324	1	1957 Studebaker & Packard Clipper	HEADLINING PULLING AWAY FROM REAR QUARTER WINDOW MOULDINGS	314	2	1956 Pass. Coupe & 2-door Sedan
FRONT FENDERS FOR SERVICE	327	4	1953 to 1957 Studebaker & 1957 Packard Clipper	HEAVY DUTY BRAKES - Bonded Lining	333	3	Passenger Cars with 10" & 11" Brake Drums
FRONT LICENSE PLATE BRACKET	338	7	3E Trucks	HEAVY DUTY STRIPPED ENGINE ASSEMBLY	339	6	3E1, 3E5 and 3E10 Trucks
FRONT PUMP & RELATED PARTS - Changes	316	5	Ultramatic	HESITATION ON ACCELERATION WITH COLD ENGINE	337	3	Models with 488L Carb.
FRONT PUMP STATOR SUPPORT & BACKING PLATE, Use of	333	2	Flightomatic	HIGH RANGE CLUTCH BURNING	327	8	Ultramatic
FRONT SEAT CUSHION COVER DAMAGE	338	1	1958 2-door Models	HIGH RANGE CLUTCH BURNING	338	3	Ultramatic Transmission (Packard)
FRONT SEAT LEAN-BACK, Divided	312	1	1956	HIGH RANGE CLUTCH PROBLEMS	320	5	55th & 56th Series Packard
FRONT SEAT MODIFICATIONS	335	6	1958 2-door Studebaker	HINGE TYPE WEATHERSTRIP	331	6	1956 Packard & Clipper
FRONT SUSPENSION NOISE	314	4	All Models	HOOD DOVETAIL SPRING	327	2	All Models
- G -				HOOD LOCK DOVETAIL SPRING	335	7	58LS-K9 Packard
GASKET & SEAL KITS (Warner Gear)	316	6	Flightomatic	HOOD ORNAMENT STUD Strikes Radiator Cap	324	5	57L
GASOLINE TANK ATTACHMENT	315	4	1956 Pass.	HOOD PROP HOLE	313	1	1956 Hawk Series
GENERATOR DRIVEN POWER STEERING PUMP	337	3	Models equipped with Air Conditioning	HOOD REINFORCEMENT	327	3	1956 & 1957 Stude. & 1957 Packard Clipper Sedans & Station Wagons
GLOVE COMPARTMENT LOCK KIT	317	1	1956 C & K				
GOVERNOR ASSEMBLY - Flightomatic	320	4	All Models except Golden Hawk				
GOVERNOR OR VALVES STICKING (Warner Gear)	317	4	Flightomatic				

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
H - Cont'd.				O - Cont'd.			
HORN TESTING AND ADJUSTMENT - Sparton Horn	335	4	1958 Pass.	OIL COOLING UNIT LEAKS Flightomatic	327	2	1957 Golden Hawk & Packard Clipper
HOUSE TRAILER TOWING, Trucks Modified for	316	7	2E13	OIL DISTRIBUTOR TUBE POSITION in Output Shaft	321	3	Flightomatic
- I -				OIL LOSS	319	5	56G Ultramatic
IGNITION & STARTING SWITCH	328	5	1955 - 1957 Stude. Cars & Trucks	OIL LOSS at breather	339	3	Ultramatic
INSTALLATION OF BATTERIES	323	2		OIL PAN Damage	323	1	Flightomatic
INSTALLATION OF NEW FLANGE on Power Steering Gear Shaft	331	1	1955-57 Stude. & 1957-58 Packard	OIL PRESSURE SIGNAL Flight switch	321	1	1957 Sedan & Station wagon
INSTRUMENT BOARD CRASH PAD	330	3	57L	OIL PUMP ROTOR & ULTRAMATIC CONVERTER PUMP SHAFT	331	4	54th, 55th, & 56th Series Packard & Clipper & 1956 Golden Hawk Flightomatic
INSTRUMENT BOARD & INSTRUMENT GROUNDING	312	4	1956 Hawk Series	OIL STRAINER ASSEMBLY OVERDRIVE TRANSMISSION, New	336	11	
INTAKE VALVE SPRING RETAINERS	317	2	56J	OVERDRIVE TRANSMISSION Removal	320	4	57G
INTERFERENCE Front End of Propeller Shaft & Body Floor Pan	330	2	58HC & 58HK Hawk	OVERHEATING, Clutch & Band Failure	313	2	56J
- L -				- P -			
LIFTER REPLACEMENT	321	4	1954 Comm.	PAINT FORMULATIONS	313	1	1956 Pass. & Station Wagons
LIGHT BULB - Mazda No. 53	315	8		PAINT FORMULATIONS	319	1	1957 Pass. & Station Wagons
LOW SPEED GOVERNOR	315	3	Ultramatic	PAINT FORMULATIONS	319	7	3E Trucks
- M -				PAINT FORMULATIONS	327	6	1957 Packard Clipper
MANUAL VALVE CONTROL LEVER Inner Stop	324	5	55th Series Ultramatic	PAINT FORMULATIONS	328	5	1957 Models - Not on Scotsman
MANZEL REPAIR STANDS	315	8		PAINT FORMULATIONS	330	3	1957 Packard Clipper
- N -				PAINT FORMULATIONS	331	2	1958 Studebaker & Packard Passenger Cars & 3E Series Trucks
NEW MODELS	318		1957 Pass. Cars & Trucks	PAINT FORMULATIONS on Scotsman	328	5	
NEW MODELS	329		All 1958 Models	PARKING BRAKE CABLE Interference	313	3	1/2 & 3/4 ton trucks
"NO REVERSE" Complaints - Warner Gear - Automatic	315	4		PARKING and DIRECTIONAL LIGHT LENS Installation	337	5	1958 Studebaker Except Hawk Models
NOVI AIR CONDITIONING Service Stations	316	3		PARKING and DIRECTIONAL LIGHT HOUSING ineffective Ground and Water Leaks	337	5	1958 Studebaker Except Hawk
NOVI TRUNK INSTALLED AIR CONDITIONER, Testing	330	1					
- O -							
OIL COOLER	322	4	55th & 56th Series Packard				

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
P - Cont'd.				R - Cont'd.			
POWER BRAKE Unit Noise	319	4	All Models	RADIO, Custom with Automatic Tuning	320	7	1957 Packard
POWER BRAKE Unit Noise	322	1	1956-1957 Studebaker & 1957 Packard Clipper	RADIO, How Conditions Affect Reception	317	4	
POWER STEERING	328	6	3E Series Trucks	RADIO IGNITION NOISE PICKUP	323	3	1957 Packard Clipper
POWER STEERING Gear Noise	314	3	1956 Models	RADIO Rear Seat Speaker	321	4	1957 Stude.
POWER STEERING Gear Noise & Adjustments	317	3	1956 Models	RADIO SERVICE	314	2	1956 Pass. Cars & Trucks
POWER STEERING Gear & Pump Changes	315	7		REAR AXLE Lubricant	333	3	
POWER STEERING not Effective on Left Turns	321	4	1957 Stude.	REAR AXLE PINION Depth Setting	330	3	1956 Packard & Clipper
POWER STEERING Pump Reservoir Cap	319	6	55th & 56th Series Packards	REAR AXLE SHAFT Bearing Lubrication	327	2	1957 Stude. & Packard Clipper
POWER STEERING Pump Servicing	330	1	All Model Studebakers & 1957 & 1958 Packards	REAR BUMPER SUPPORT ARMS	319	6	55th Series Packards
PRIMARY BRAKE Shoe Lining Length	324	1	1957 Stude. & Packard Clipper	REAR BUMPER-TO-BODY GRAVEL SEAL	317	1	1956 Sedan
PRODUCT REPORTS	312	4		REAR BUMPER-TO-TAIL LIGHT CLEARANCE ASSEMBLY	319	4	1957 Sedan
PROPELLER SHAFT Diameter	333	4	58H-K & 58L-K	REAR CLUTCH FRICTION DISC	328	2	Flightomatic
PROPELLER SHAFT Support Spacer	321	4	3E40 Trucks	REAR EXTENSION HOUSING BEARING Removal	336	4	Flightomatic
PROPELLOR SHAFT & UNIVERSAL JOINT ASSEMBLIES	324	6	3E Series Trucks	REAR FENDER FIN Repair	315	5	Stationwagon & 56J
PROPER COMPLETION OF B866 - Returned parts Identification Tag	337	1		REAR PROPELLER SHAFT	315	4	56B.W.F.D.
PUSH BUTTON CONTROL	327	6	1956 Packard & Clipper Models	REAR QUARTER BELT Moulding	337	2	1958J
PUSH BUTTON CONTROL Inoperative	322	4	56th Series Packard	REAR SHOCK ABSORBERS	336	12	3E1 Trucks
PUSH BUTTON CONTROL VENT	322	4	56th Series Packard	REAR SHOCK ABSORBER Noise	338	2	1957-58 Stude. and Packard Pass. Cars
PUSH BUTTON RETAINING CLIP	324	4	56th Series Packard	REAR SHOCK ABSORBER Noise	325	4	1957 Stude. & Packard Clipper
- R -				REAR UNIVERSAL JOINT REPAIR KIT	335	7	Models 2401, 2501, 2601, 5400 & 5401 57L Models
RADIATOR INLET HOSE COLLAPSING	331	6	1955-56 Packard & Clipper	REAR WINDOW PANELS REDUCTION OF FAN NOISE AND IMPROVED COOLING	322	3	
RADIATOR INLET HOSE REINFORCING SPRING	337	6	1955-56 Packard & Clipper	REPLACEMENT OF CLIMATIZER & DEFROSTER MOTORS	338	3	1958 Packard Hawk Models
RADIO ANTENNA	323	3	1957 Packard Clipper	RETURNED PARTS IDENTIFICATION TAG - Proper completion of B866	330	2	1956-57 Stude. & 1957 Packard Clipper
RADIATOR TOP TANK Collapsing	335	6	All Models	RIGHT REAR FENDER RUMBLE	337	1	
					325	4	Scotsman

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
R - Cont'd.				S - Cont'd.			
ROAD NOISE and/or WATER LEAKS IN REAR SEAT COMPARTMENT	336	2	1956-57 & 1958 Sedan	STARTER MOTOR BENDIX FOLO-THRU DRIVE	337	3	1951-1958 Champion Engine
ROCKER ARM ADJUSTING SCREW	320	4	Stude. 259 & 289 cu.in. Engine	STARTER MOTOR PINION ADJUSTMENT	317	2	56J
RUBBER CEMENT & SEALER REMOVAL from New Vehicles	323	1		STATOR SUPPORT & BACKING PLATE ASSEMBLY - (Warner Gear)	316	6	Flightomatic
- S -				STEERING GEAR LUBRICANT	313	1	All thru 1956 Ross Gear
SAFETY CHECK CAMPAIGN	338	1		STEERING GEAR LUBRICANT LEVEL with Standard Steering	325	1	57B, 57H, & 57L
SAFETY LATCH & HOOD LOCK	314	5	1956 Hawk Series	STEERING KNUCKLE NEEDLE BEARINGS	333	3	1958 Stude. & Packard Pass.
SEALER & RUBBER CEMENT REMOVAL from New Vehicles	323	1		STEERING KNUCKLE PIN NUT	333	3	1958 Stude. & Packard Pass.
SEAT CUSHION SPRING LUBRICATION	314	2		STEERING POST BRACKET & BRACE ROD INSTALLATION, Time Allowance	325	5	1957 Packard Clipper Model
SERVICE OPERATION TIME GUIDE, operation Addition	322	2	All 56-57 C & K	STEERING POST FLANGE PIN	336	4	1955-57 Stude. & 1957-58 Packard with Power Steering
SERVICE SUGGESTIONS FOR THE FLIGHTOMATIC TRANSMISSION	328	2		STEERING POST FLANGE PIN	337	7	1958 Packard Models with Power Steering
SERVICE TRANSMISSIONS - Standard & Overdrive	333	2	1958 Stude. & Packard	STEERING RING	336	2	1958 Stude. and Packard
SERVICING THE PACKARD ANTENNA	328	5	1955-56 Packards	STEERING WHEEL SHAKE	325	4	57B & 57H Sedan
SERVICING THE SCOTSMAN MODELS	326			STOP LIGHT SWITCH - with Torsion Level Suspension	328	5	1955-56 Packard & Clipper
SCOTSMAN PICKUP	334		3E1	SUPERCHARGER - Carburetor Air Chamber	320	3	Golden Hawk 57H-K
SHIFT SEQUENCE PLATE - 5 speed Transmission	313	4		SUPERCHARGER DRIVE BELT POSITION	323	2	Studebaker 57H-K and Packard Clipper 57L
SHIFT SPEEDS	315	2	1956 Golden Hawk - Ultramatic	SUPERCHARGER PARTS FOR SERVICE	321	1	Golden Hawk & Packard Clipper
SHOCK ABSORBER NOISE	336	4	1957 & 1958 Pass. Cars	SUPERCHARGER PLANETARY RACE REPLACEMENT	320	1	57H-K Golden Hawk & 57L Packard Clipper
SLIPPAGE	323	2	Flightomatic	SUPERCHARGER SLIDING PULLEY FLANGE ASSEMBLY	319	4	Golden Hawk 57H-K
SPARE TIRE LOCATION, Models with Pickup Body	325	5		SUPERCHARGER SLIDING PULLEY STOP WASHER	320	3	Golden Hawk 57H-K
SPARK & DISTRIBUTOR MODIFIER ASSEMBLY	317	5	2E7, 2E13, & 2E28 Trucks				
SPARK PLUG CABLES	333	6	1958 Packard				
SPARK PLUG REMOVAL WITH AIR CONDITIONING	322	3	57L-Y Models				
SPARK PLUG REPRESENTATIVES	319	8					
SPARK PLUGS	313	4	V8 2E Series Trucks				
SPARK PLUGS	315	3	N-8-64B				
SPARK PLUGS	331	2	259 & 289 cu.in V-8 Engines				
SPEEDOMETER PINION Information	322	3	57L				
STARTER MOTOR	327	8	3E5 Truck				

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
- T -				T - Cont'd.			
TAIL GATE RATTLES	325	1	Studebaker & Packard Clipper Station Wagons - 1957	TWIN TRACTION DIFFERENTIAL FILLER PLUG INTERFERENCE	319	6	Packard
TAXICAB CARBURETOR THROTTLE LINKAGE	336 313	11 2	BBR1 2808S 56J Ultra-matic	TWIN TRACTION DIFFERENTIAL NOISE	327	3	1957 Stude. & Packard Clipper
THROTTLE LINKAGE ADJ THROTTLE LINKAGE	313	2	56B 56H	TWIN TRACTION OPERATION	339	3	
ADJUSTMENT PROCEDURE	328	3	Flightomatic	TWIN TRACTION REAR AXLE ASSEMBLIES	325	3	All Pass. Cars & Trucks
TIME ALLOWANCE CHANGE (Clipper Time Guide)	324	5	1957 Packard Clipper	TWIN TRACTION REAR AXLE IDENTIFICATION	319	5	1957 Stude. Pass. Cars & 2E & 3E Series Trucks
TIME ALLOWANCE CHANGES (Packard Time Guide)	323	3	1957 Packard	TWIN TRACTION REAR AXLE New	339	2	
TIRE PRESSURE - captive Air Tires	327	3	2E7 & 2E12 Trucks	TWIN TRACTION REAR AXLE THRUST PIN, out of Position	339	2	All Models
TORQUE CONVERTER	317	5	1956 Packard & Clipper & 1956 Golden Hawk	TYPOGRAPHICAL ERROR	325	5	
TORQUE CONVERTER	331	6		- U -			
TORQUE CONVERTOR ASSEMBLY	316	6	56G Pass. Flightomatic	ULTRAMATIC CONVERTER PUMP SHAFT & OIL PUMP ROTOR	331	4	54th & 56th Series Packard & Clipper & 1956 Golden Hawks
TORQUE CONVERTER ASSEMBLY	336	3	1957 & 1958 Models with Supercharger	ULTRAMATIC DRIVE CONTROL ASSEMBLY	338	4	Packard Part No. 423800 Prior to Gear Shift
TORQUE CONVERTERS	339	4	1956 Packard & 1956 Stude. Golden Hawk	ULTRAMATIC TRANSMISSION CHANGES	315	4	
TORQUE CONVERTERS EXCHANGE PRICE LIST	313	2		UNDERDASH AIR CONDITIONER SERVICE & SERVICE STATION DIRECTORY	336	5	
TORSION BARS, Long	320	7		U. S. ROYAL TIRES	337	3	1958 Passenger Cars
TORSION LEVEL CONTROL SWITCH	319	6	55th & 56th Series Packards	UNIVERSAL JOINT CROSS & BEARING KITS	330	1	1957 & 1958
TORSION LEVEL CONTROL SWITCH	324	4	1955 Packard	UNIVERSAL JOINT LUBRICATION FITTING	327	2	1957 Stude. & Packard Clipper
TORSION LEVEL SUSPENSION, Erratic Action of	325	5	55th & 56th Packard	UPHOLSTERY WEAR AT INSIDE DOOR HANDLE	337	3	1958
TRANSMISSION END PLAY	315	3	Flightomatic	- V -			
TRANSMISSION FRONT CASE BUSHING	333	1	Flightomatic	VALVE BODY-TO-FRONT SERVO TUBES	327	3	Flightomatic
TRANSMISSION FRONT CLUTCH DISK	314	2	Flightomatic	VALVE BUZZ	333	1	Flightomatic
TRANSMISSION GEAR CLASHING	339	5	58G-Y1 Taxicab	VALVE CLEARANCE ADJUSTMENT WITH AIR CONDITIONING	322	2	57L-Y Models Golden Hawk
TRIM MOULDING	337	6	1958 Packard Hawk	VALVE LIFTER TOOL	315	2	
TRUCK CHANGES	314	5	2E11 & 2E12	VALVE SPRING IDENTIFICATION	335	5	1956-1957 Flightomatic
TRUCK CHANGES	315	8	2E13 & 2E14	VALVE SPRING RETAINERS	325	1	57th Series Packard & 1956 Stude. Golden Hawk Engines
TRUCK EXHAUST SYSTEM	327	8					
TRUCKS CLIMATIZER HEAT DISTRIBUTION	335	8	Trucks				
TRUCKS MODIFIED FOR HOUSE TRAILER TOWING	316	7	2E13				
TRUNK LOCK KIT	317	1	1956 - C & K				
TWIN TRACTION DECAL INSTRUMENT PANEL	339	1	All Models				
TWIN TRACTION DIFFERENTIAL	311		2E5-2E6-2E7				

REFERENCE	BUL. NO.	PAGE	MODEL	REFERENCE	BUL. NO.	PAGE	MODEL
Y - Cont'd.				- W -			
VALVE SPRING RETAINERS	325	1	57th Series Packard and 1956 Stude. Golden Hawk Engines	WATER LEAKS and/or ROAD NOISE IN REAR SEAT COMPARTMENT	336	2	1956-57-58 Sedans
VALVE SPRING & SPRING RETAINER	330	2	185 cu. in. Engines V8	WHEEL & TIRE RUNOUT WINDOW REGULATOR ASSEMBLY	317	4	1955 & 1956 Packard & Clipper
VALVE STEM CAPS	312	1		WINDOW REGULATOR ASSEMBLY	320	7	Packard 5522 & 5622
VALVES OR GOVERNOR STICKING (Warner Gear)	317	4	Flightomatic	WINDSHIELD WASHER COVER AND PUMP ASSEMBLY	322	3	1955-56 Packard Clipper
VENTING GASOLINE TANK - wheel drive	336	11	Truck	WINDSHIELD WASHER NOZZLE	322	3	1955-56 Packard Clipper
VIBRATION	328	1	1957 Packard Clipper Sedan & 1957 Stude. President	WINDSHIELD WIPER KIT, Electric - 12 volt	339	1	Studebaker & Packard
VIBRATION NOISE	330	2	56G Scotsman with O. D. Transmission		312	4	2E Series Trucks

STUDEBAKER-PACKARD CORPORATION

SOUTH BEND 27, INDIANA