

# SPECIAL "SELL MORE PARTS" BULLETIN

PACKARD PARTS for PACKARD CARS

PACKARD SERVICE for PACKARD OWNERS

SERVICE STORES DIVISION  PACKARD MOTOR CAR COMPANY

DETROIT, MICH.

PACKARD DISTRIBUTERS AND DEALERS

NO. 140

ATTENTION OF General Manager, Service Manager  
and Stores Manager

DATE Jan. 11, 1935

*File + made change in book  
+ cards  
JBB*

Many complete assemblies, part 213463, radiator shutter thermostat and covers, are being returned to the factory as defective, when only the sylphons are at fault, consequently many replacements of these assemblies are ordered where new sylphons only are actually needed.

Piece 223131, sylphon assembly is interchangeable on all models from the 1001 to the 1208, inclusive. This important information should be posted on:

- (a) Page 133, Packard Eight Parts List
- (b) Page 77, Packard Twelve Parts List
- (c) Page 35, Packard Twelfth Series Parts List
- (d) All stock ordering and record cards

In cases of failure of the thermostat sylphon assembly, remove all the operating mechanism before returning to us and order for replacement only the SYLPHON ASSEMBLY, part 223131. A sharp change in the prices of these two parts will become effective shortly, and it will be advantageous to you to become familiar with our recommendations on the handling of these replacements.

Yours very truly,

PACKARD MOTOR CAR COMPANY



B. R. Horsley  
Manager Service Stores Division

WFF:ES  
(950)