



**Packard** **SERVICE TECHNICAL**  
**Bulletin**

49T-15, Dealer 11

To: REGIONS, ZONES AND DEALERS


Subject: FRONT DOOR WINDOW CHANNEL INSPECTION

A number of cars were produced recently in which it is possible that the front door channels and window stops are not properly located.

For a short time it is suggested that the front door trim panels be loosened at the bottom and pulled out sufficiently to check the bottom of the window channels. If the channels are spread sufficiently to allow the glass to come out of the runway, the channels should be fastened in place.

The stops should also be checked to be sure that they are set to prevent the windows being lowered too far.

Very truly yours,



N. A. Lull  
Service Technical Manager

**important • important • important • important • important**