



**Packard** **SERVICE TECHNICAL**  
**Bulletin**

49T-23, Dealer 18

October 13, 1949


To: REGIONS, ZONES AND DEALERS

Subject: UNNECESSARY REPLACEMENT OF TRANSMISSION  
GEARS

When reconditioning transmissions all gears should be carefully inspected before replacement. Inspection of returned gears indicates that the majority of transmission countershaft gear clusters are changed unnecessarily.

Unless the teeth are definitely damaged due to chipping, scoring or excessive wear, countershaft gears should not be renewed.

Very truly yours,



J. A. Carr, Manager  
Parts and Service Department

**important • important • important • important • important**