

Packard **SERVICE TECHNICAL** **Bulletin**

*Read and return to office
Tupper*

50T-10, Dealer 8
March 2, 1950

To: ZONES AND DEALERS

Subject: 14MM SPARK PLUGS - 23RD SERIES

All 23rd Series engines now being built in production are equipped with 14MM spark plugs.

The gap setting for these plugs is the same as that specified for the 10MM plug -- .025 to .030 inch; however, the torque tightness differs. The 10MM plugs should be tightened to a torque of 10 to 14 ft. lbs. and the 14MM plugs to a torque of 25 to 35 ft. lbs.

The 14MM plugs are carried under the following part numbers:

- 419915 Auto-Lite A-5-H
- 419917 AC 44-5
- 419918 Champion J-8

Very truly yours,

J. A. Carr
J. A. Carr, Manager
Parts and Service Department