

Packard **SERVICE TECHNICAL**
Bulletin

50T-12, Dealer 9
March 2, 1950

To: ZONES AND DEALERS

Subject: ULTRAMATIC DRIVE OIL PUMPS


Due to various design changes in details of the front and rear oil pump assemblies in Ultramatic Drive units, the major details such as the pump bodies, cover plates, and rotor sets will no longer be furnished separately as listed in the Ultramatic Drive Parts List.

A number of these major detail parts in the later type pumps are not interchangeable with those in the early type pumps; however, the late and the early type pump assemblies are interchangeable.

Complete pump assemblies will be furnished under the following part numbers:

423186 Rear Oil Pump Assembly 2301-02-06-22-32-33
421634 Front Oil Pump Assembly 2301-02-06-22-32-33

Very truly yours,



J. A. Carr, Manager
Parts and Service Department

AED:ms