

Packard **SERVICE TECHNICAL**
 **Bulletin**

50T-13, Dealer 10
March 10, 1950

To: ZONES AND DEALERS


Subject: ULTRAMATIC DRIVE GOVERNOR REPLACEMENT

A number of Ultramatic Drive Governor assemblies, reported as being defective, have been returned to the Factory for credit.

Inspections of these units have revealed that the majority were not defective but required either cleaning or freeing up of the vent valve.

Before a governor assembly is condemned and replaced, it should be disassembled and checked as outlined on pages 12 and 13 of the booklet "Servicing the Ultramatic Drive."

Very truly yours,


J. A. Carr, Manager
Parts and Service Department

AED:ms