

SERVICE TECHNICAL

Dulletin



50T-28 August 10, 1950

To: ZONES

Subject: TIRE SIZE CORRECTION - MODEL 2332

Service Counselor, Vol. 23, No. 5, May 1, 1949, shows the tire size as being 15 X 8.20 for the Super Eight Convertible, model 2332. This is incorrect. The proper tire size for this model is 15 X 8.00. Please change your Counselor accordingly.

A limited number of Super Eights were equipped with 15 X 8.20 tires at the beginning of 23rd Series production; however, the 8.00 tires were not available at the time and only a few cars were affected.

Very truly yours,

J. A. Carr, Manager

Parts and Service Department

AED:ljk