



**Packard** SERVICE TECHNICAL  
Bulletin

50T-38, Dealer 30

September 18, 1950

To: ZONES AND DEALERS

Subject: BATTERY CABLE CAMPAIGN - 24TH SERIES

All 24th Series vehicles, both in the hands of Dealers and in Zones should be checked IMMEDIATELY for possible interference between the air cleaner and the negative battery cable (battery to starter switch cable).

Approximately 150 cars are affected and this applies only to those cars having an engine serial number below 203570 and equipped with an Auto-Lite starter and an oil bath cleaner.

The cable on these vehicles is part number 416404 and is 28 inches long measured from the centers of the terminal holes. If an interference or very little clearance exists between the cable and air cleaner, this cable should be replaced with cable part number 416471 which is two inches longer.

Replaced cables may be retained in service stock, for use with a standard air cleaner or Delco equipment, or may be returned on an R.F.A. in the usual manner. Labor for 0.3 hr. will be allowed if cables are returned. The longer cables, 416471, should be ordered as required.

Yours very truly,

*J. A. Carr*  
J. A. Carr, Manager  
Parts and Service Department

JAC:ljk  
AED