



Packard **SERVICE TECHNICAL** **Bulletin**

51T-5, Dealer 4
February 14, 1951

TO: ZONES AND DEALERS


SUBJECT: GOVERNOR ADAPTOR SCREEN - ULTRAMATIC DRIVE

The numerous Product Reports received from the field on governors sticking because of dirt or foreign matter has resulted in the adoption of a filtering screen in the governor adaptor.

Ultramatic Drive units having a serial number above 26127 and 17231 incorporate the late type adaptor.

When a governor is removed for cleaning or when the fluid is changed at the 25,000 mile intervals, it is recommended that the adaptor be removed and the screen cleaned.

Yours very truly,



J. A. Carr, Manager
Parts and Service Department

JAC/hs