



Packard SERVICE TECHNICAL

Bulletin

52T-21
Dealer 14
June 12, 1952

To: ZONES AND DEALERS


Subject: ULTRAMATIC HIGH RANGE CLUTCH PLATES -- REPLACEMENT

Warning: It has been brought to our attention that certain vendors are offering for sale to Packard dealerships relined high range Ultramatic clutch plates.

Under no circumstances should these be used for replacement parts in Ultramatic servicing; these plates may be distorted, worn, warped, or dimensions out of limits, or may be relined with improper material.

The practice of using these relined plates must not be followed, as by so doing damage to the Ultramatic mechanism may result; furthermore, this voids our warranty covering Packard approved parts replaced in the Ultramatic Drive unit itself.

Very truly yours,


J. A. Carr, Manager
Parts and Service Department

JAC:jh