

ackard **SERVICE** **TECHNICAL** **Bulletin**

52T-25
Dealer 18
July 2, 1952

To: ZONES AND DEALERS

Subject: EASAMATIC, REPAIR KITS AND WARRANTY

There are two repair kits now available to the field for the Easamatic Power Unit. These kits, Brake Power Unit Repair Kit, Part Number 436318, and Brake Power Unit Piston Packing Kit, Part Number 436319, will contain the required parts to repair the Easamatic Assemblies in the field and eliminate the replacement of complete assemblies.


The warranty on Bendix parts, used in the repair of these units, is the same as the warranty that applies to Packard parts.

The Piston Packing Kit, Part Number 436319, may be installed without removing the power unit from the car; the suggested time is 1.3 hours.

The installation of the Brake Power Unit Repair Kit, Part Number 436318, cannot be installed without removing the complete Easamatic Assembly from the car. It will be necessary to use both repair kits when performing a complete reconditioning operation. The suggested time for the complete reconditioning operation is 3.3 hours, which includes the R & R of the assembly.

As of July 15, 1952, no more complete Easamatic Power Unit assemblies are to be returned for credit; repairs must be made in the field.

Very truly yours,



J. A. Carr, Manager
Parts and Service Department

JAC:meg