

Packard **SERVICE TECHNICAL** **Bulletin**

10 ✓

52T-8
February 5, 1952

To: ZONES ONLY

Subject: WATER LEAKS

We are receiving numerous reports regarding water leaks at the windshield and wiper pivots with very little information as to exact location and just what was done to correct the leaks.

The wiper pivot leak reports do not state whether the pivots were loose, gaskets out of place, or just needed sealing.

The windshield leak reports do not state the exact location of the leaks and what was done to correct the leaks.

Manufacturing and inspection are making every effort to correct water leaks in the car. Zone Product Reports with accurate information for the next 30 days would be very helpful.

Very truly yours,

J. A. Carr
J. A. Carr, Manager
Parts and Service Department

JAC:pam