

The logo features a large, stylized letter 'P' on the left. Inside the 'P' are illustrations of a wrench and a screwdriver. To the right of the 'P' is the word 'Packard' in a serif font. Further right is a dark rectangular box containing the words 'SERVICE' and 'TECHNICAL' in white, bold, sans-serif capital letters. An arrow points from the 'P' towards a large, stylized letter 'B' on the right. To the right of the 'B' is the word 'ulletin' in a serif font, completing the word 'Bulletin'.

Packard SERVICE TECHNICAL Bulletin

53T-22
Dealer 19
October 28, 1953

TO: ZONES AND DEALERS

SUBJECT: LOW SPEED COOLING - 24th, 25th, 26th Series

The Factory Parts Warehouse can supply heavy duty Service fans for 24th, 25th and 26th Series cars in which coolant boiling is reported at idle or at low speeds in heavy traffic.

The greater capacity fan is not intended as a general service replacement and should only be used when boiling occurs because of sustained idling periods and low speed driving.

The new fans are carried under Part Number 436856.

Very truly yours,

A handwritten signature in cursive script that reads 'J. A. Carr'.
J. A. Carr
General Service Manager

JAC:mg