



Packard SERVICE TECHNICAL Bulletin

53 T-24
Dealer 21
December 3, 1953

TO: ZONES AND DEALERS

SUBJECT: AIR CONDITIONING FLAT RATE TIME ALLOWANCES-
CHANGES IN FLAT RATE MANUAL


Flat rate time allowances have been established on servicing the Air Conditioning system and are listed on the attached sheets.

The following changes are to be made in your Flat Rate Manual.

Operation 20-23 Door Lock Striker - Fit. The decimal point should precede the figure 3 making the operation read: .3 hour instead of 3. hours.

Operation R-14 Ultramatic Inspection and Fluid Change. This operation was covered in Service Technical Bulletin 49T-38, Dealer 29, December 19, 1949. Please delete this operation R-14 from the Flat Rate Manual as this particular inspection is no longer recommended.

Very truly yours,



J. A. Carr
General Service Manager

JAC:rf

Att.