



Packard SERVICE TECHNICAL

Bulletin

53T-25
Dealer 22
December 14, 1953

TO: ZONES AND DEALERS

SUBJECT: SERVICEMAN'S TRAINING BOOK -
"PACKARD AIR CONDITIONING" REVISIONS

The following revisions should be made in your Serviceman's Training Book "Packard Air Conditioning."

Page 22, "Replacing Dehydrator-Filter or Sight Glass," second paragraph. At the end of the paragraph after "Figure 16" add "See note A." On the "NOTES" page following page 33 add the note "A - The dehydrator-filter also should be replaced whenever it has been positively determined that there has been a leak at any fitting in the low pressure side of the system, with a resultant high head pressure, indicating that air and moisture have been drawn into the system."

Page 22, "Replacing Dehydrator-Filter or Sight Glass." Delete the fourth paragraph which states that the dehydrator-filter should be replaced if the compressor fails.

Page 25, "Replacing an Inoperative Compressor," step 6. Delete the complete sentence and after it add "See note B." On the "NOTES" page add the note "B - Disconnect the liquid line from the dehydrator-filter, on the inlet side of the dehydrator, and cap the dehydrator immediately."

Page 25, "Replacing an Inoperative Compressor", step 9. Delete the complete sentence and add "See note C." On the "NOTES" page add the note "C - Reconnect the liquid line to the dehydrator-filter. Note: If any free moisture has been found in the faulty compressor or if the system has been exposed to the atmosphere for a prolonged period of time, the dehydrator-filter should be replaced."

Very truly yours,


J. A. Carr
General Service Manager

JAC:rf