

Packard SERVICE TECHNICAL Bulletin

To: ZONES


53T-27

January 15, 1954

Subject: 1953 SERVICE TECHNICAL BULLETIN INDEX

53T-1	Dlr. 1	Feb. 2, 1953	Campaign - Sticking Accelerators, Convertible, Mayfair, Cavalier, Patrician, 26th Series
53T-2	Dlr. 2	Jan. 20, 1953	Carburetor Choke Setting Changed, "WCFB" Carburetor, 26th Series
53T-3	-	Jan. 20, 1953	Changes in Ultramatic (Confidential) REVISED
53T-4	Dlr. 3	Feb. 5, 1953	Direct Drive Clutch Fails to Disengage - Ultramatic
53T-5	Dlr. 4	Feb. 6, 1953	Wiper Cable Slippage - 26th Series
53T-6	Dlr. 5	Feb. 13, 1953	"WCFB 985S" Carburetor Troubles, 26th Series Causes and Corrections
53T-7	Dlr. 6	Feb. 23, 1953	Undercoating Caution
53T-8	-	Mar. 13, 1953	Direct Drive Clutch Plate - Ultramatic 9" Diameter
53T-9	Dlr. 7	Mar. 23, 1953	Noisy Power Steering Pumps - 26th Series
53T-10	Dlr. 8	Mar. 23, 1953	Drip Moulding Leaks - Mayfair - 26th Series
53T-11	Dlr. 9	Jun. 4, 1953	New Cooling System Thermostats (Capsule Type) 26th Series
53T-12	Dlr. 10	Jun. 29, 1953	Continental Tire Carrier - Rattles 26th Series
53T-13	Dlr. 11	Jun. 29, 1953	Air Cleaner Alignment 4-Barrel Carburetor
53T-14	-	Jul. 10, 1953	Changes in Ultramatic (Confidential)
53T-15	Dlr. 12	Jul. 27, 1953	Packard Wonder Seal (Part Number 98739)
53T-16	Dlr. 13	Aug. 10, 1953	Rear Axle Hypoid Break-In Oil-26th Series
53T-17	Dlr. 14	Aug. 19, 1953	Undercoating Caution - Air Conditioned Cars
53T-18	Dlr. 15	Sep. 21, 1953	Heavy Duty Transmission Gears - 2633
53T-19	Dlr. 16	Sep. 23, 1953	Compressor Driving Pulley Run-Out Air Conditioned Cars
53T-20	Dlr. 17	Sep. 23, 1953	Air Conditioning Service Data
53T-21	Dlr. 18	Oct. 21, 1953	High Speed Vibration - 24th, 25th, 26th Series Standard Transmission and Overdrive
53T-22	Dlr. 19	Oct. 28, 1953	Low Speed Cooling - 24th, 25th, 26th Series
53T-23	Dlr. 20	Dec. 2, 1953	Universal Joint and Axle Shaft Bearing Lubrication Period Revised
53T-24	Dlr. 21	Dec. 3, 1953	Air Conditioning Flat Rate Time Allowances-Changes in Flat Rate Manual
53T-25	Dlr. 22	Dec. 14, 1953	Serviceman's Training Book - "Packard Air Conditioning" Revisions
53T-26	Dlr. 23	Dec. 28, 1953	Parking Lamp Cable and Sockets
53T-27	-	Jan. 15, 1954	1953 Service Technical Bulletin Index
53T-28	Dlr. 24	Jan. 15, 1954	1953 Service Technical Bulletin Index

Very truly yours,


J. A. Carr
General Service Manager