

Packard SERVICE TECHNICAL Bulletin

55T-42
Dealer 33
September 29, 1955

To: ZONES AND DEALERS

Subject: SHOCK ABSORBERS - EXPORT - 55TH SERIES

A few reports have been received whereby some owners desire a firmer than standard ride in the 55th Series Torsion-Level suspension equipped cars.


These owners generally complain of an occasional strike through and/or rear wheel dance while driving over extreme rough roads. Heavily loaded trunk compartments with light passenger loads may also cause the car to pitch under certain road conditions.

Export shock absorbers (heavy duty type) will reduce the above conditions, however, bear in mind that the smooth boulevard ride will be reduced slightly.

The export shock absorbers may be ordered through your Zone Warehouse as follows:

Part Number 6480540	Shock Absorber Assembly Front - Models 5560-80	2
Part Number 6480536	Shock Absorber Assembly Rear - Models 5560-80	2

Very truly yours,



H. N. Johnson
Assistant Service Manager

HGL:mu