

Packard **SERVICE TECHNICAL**
Bulletin

55T-51
Dealer 42
December 2, 1955

To: ZONES AND DEALERS


Subject: REAR WINDOW OUTSIDE TRIM PLATES - 56TH SERIES

A few reports have been received of rust and tarnish appearing on the rear window outside end trim plates.

The trim plates are stainless steel and do not rust; however, they are buffed to obtain the satin like finish. After buffing a certain residue appears on the plate which in time turns dark or in some cases rust appears. It is the residue that rusts and tarnishes and not the trim plates.

The residue can be removed with one or two applications of chrome cleaner or polish cleaner.

Very truly yours,



H. N. Johnson
Assistant Service Manager

TWN:jb