



Packard

SERVICE

TECHNICAL

Bulletin

55T-55
Dealer 46
December 31, 1955


To: ZONES AND DEALERS

Subject: INDEX - SERVICE TECHNICAL BULLETINS - JANUARY 1, 1955 THROUGH
DECEMBER 31, 1955

<u>Subject</u>	<u>Zone</u>	<u>Dlr.</u>	<u>Date</u>
AIR CONDITIONING			
Air Conditioning Service Kit - 55th Series	55T-45	36	Nov. 4, 1955
BODY			
Front Underseat Heater Fan Guard - 54th Series	55T-9	8	Feb. 3, 1955
Instrument Panel Paint Schemes - 55th Series	55T-21	18	May 25, 1955
Rear Cigar Lighters - 5582-87	55T-14	12	Mar. 10, 1955
Rear Window Outside Trim Plates - 56th Series	55T-51	42	Dec. 2, 1955
Stained Headlining - 55th Series Clippers	55T-30	21	June 28, 1955
Stained Headlining - 55th Series Clippers - Correction	55T-44	35	Oct. 20, 1955
Windshield Weatherstrip and Moulding Retainers - 55th Series	55T-10	9	Feb. 10, 1955
Windshield Weatherstrip Retainer - Revised - 55th Series	55T-34	25	July 15, 1955
CARBURETOR			
AC Carburetor Air Cleaner - 5540	55T-24	19	June 6, 1955
Gasoline Fumes - 5560-80	55T-41	32	Sep. 14, 1955
ELECTRICAL			
Battery - Negative Terminal Grounded - 56th Series	55T-49	40	Nov. 17, 1955
Rear Cigar Lighters - 5582-87	55T-14	12	Mar. 10, 1955
Storage Battery - Replacement	55T-15	13	Mar. 28, 1955
12-Volt Battery Characteristics	55T-3	3	Jan. 19, 1955
ENGINE			
Incorrect Ignition Timing - 5540	55T-39	30	Aug. 26, 1955
Oil Consumption - 55th Series	55T-19	16	May 23, 1955
Rocker Lever Shaft Holes - Oil Control - 55th Series	55T-16	14	Mar. 28, 1955
Rocker Lever Shaft Holes - New Shafts - 55th Series	55T-35	26	July 25, 1955
Service Engines - 55th Series	55T-33	24	July 14, 1955

<u>Subject</u>	<u>Zone</u>	<u>Dlr.</u>	<u>Date</u>
FRAME			
Reinforcement and Modifications to Handle Trailers - 55th Series Packards	55T-27	20	June 6, 1955
SHOCK ABSORBERS			
Shock Absorbers - Export - 55th Series	55T-42	33	Sep. 29, 1955
STEERING			
Binding Steering - Bendix Power Steering	55T-38	29	Aug. 26, 1955
TORSION-LEVEL SUSPENSION			
Control Switch Wire Disconnected - 55th Series	55T-13	11	Feb. 23, 1955
Limit Switch and Compensator Motor Over-travel - 55th Series	55T-2	2	Jan. 18, 1955
Load Arm Snap - 55th Series	55T-37	28	July 29, 1955
Switches Waterproofed - 55th Series	55T-36	27	July 26, 1955
Solenoids - 56th Series - Waterproofing	55T-50	41	Nov. 18, 1955
Uneven Riding Height - 55th Series	55T-1	1	Jan. 17, 1955
Uneven Riding Height - 56th Series	55T-53	44	Dec. 20, 1955
Worm Shaft Lock Ring - Replacement - 55th Series	55T-12	10	Feb. 15, 1955
ULTRAMATIC			
Converter - Rattle	55T-40	31	Aug. 29, 1955
Direct Drive Clutch Engagement - 55th Series	55T-7	6	Feb. 2, 1955
Direct Shift Valve Piston Springs - 55th Series	55T-43	34	Oct. 14, 1955
Engine Runaway - Low to High Shifts - 55th Series	55T-32	23	July 12, 1955
Low Range - Brake Functions Improperly - 55th Series	55T-17	15	Apr. 5, 1955
Push Button Control - Instructions	55T-46	37	Nov. 15, 1955
Rear Oil Pump Driver - Hardened	55T-47	38	Nov. 15, 1955
Reactor End Play - Revisions - 56th Series	55T-52	43	Dec. 6, 1955
Shift Pattern - 55th Series	55T-6	5	Jan. 26, 1955
Transmission Replacement - Caribbean (5588)	55T-20	17	June 6, 1955
Universal Joint Flange Bolt - New Type 55th Series	55T-4	4	Jan. 19, 1955
MISCELLANEOUS			
Chrome Plate Protective Coating - 55th Series	55T-31	22	June 30, 1955
Flat Rate Time Allowance	55T-48	39	Nov. 16, 1955
Air Conditioning - 55th and 56th Series			
Rear Axle - 56th Series			
Suggested Changes - 55th Series			
Headlamp Door Wind Whistle - 56th Series Clipper	55T-54	45	Dec. 23, 1955
Instrument Panel Paint Schemes - 55th Series	55T-21	18	May 25, 1955
Torque Specifications	55T-8	7	Jan. 31, 1955

Very truly yours,



H. N. Johnson
Assistant Service Manager