

Packard SERVICE TECHNICAL Bulletin

56T-16
Dealer 13
April 30, 1956

To: ZONES AND DEALERS

Subject: SERVICING AIR CONDITIONING COMPRESSORS

A recent survey of the reasons for which air conditioning compressors were returned to the factory during 55th and early 56th Series production indicated that the majority of the units could have been repaired in the field.

Compressors should be replaced only when major internal failures occur such as, bent connecting rods, broken pistons or rings, etc. Leaks, defective valve plate assemblies, etc. should be repaired or replaced as necessary in the field.

All service replacement details are listed in the Master Parts Book under Code No. 29.000. The servicing of these details are fully covered in the Air Conditioning Section of the Service Manual. No special tools are required.

The foregoing applies to units in the warranty period as well as to those out of warranty.

Very truly yours,



T. W. Nertney
Service Technical Manager

AED:mu