

ackard **SERVICE TECHNICAL** Bulletin

56T-17
Dealer 14
April 30, 1956

To: ZONES AND DEALERS

Subject: ENGINE DETONATION - SUPPLEMENT

Please refer to your Service Technical Bulletin 56T-14, Dealer 11, dated April 3, 1956 on the above subject.

The distributor kits supplied for the 5680 models have the shaft, cam and governor weight springs assembled into one unit, therefore install this unit as an assembly. Install the new vacuum unit and identification number plate furnished in the kit.

Delete items 3 and 4 from the instructions shown in the bulletin.

Very truly yours,



T. W. Nertney
Service Technical Manager

HGL:mu