

REFER TO THIS LETTER BY NUMBER

PACKARD MOTOR CAR COMPANY

DETROIT, MICHIGAN

TO BE NOTED AND INITIALED BY

To PACKARD DISTRIBUTERS AND DEALERS

January 24, 1936

Subject PARTS PRICE BOOK AND SERVICE CHARGE MANUAL CHANGES

Effective - February 1, 1936

Gentlemen:

In order to conform to a similar change by the Manufacturer of Piston Rings, we are changing our Suggested List Price from 24¢ to 22¢ on each of the following numbers:

163881	164631	164634	179868	179874	202801	202804	213980	213989
163882	164632	179864	179870	179876	202802	202805	213981	228517
164630	164633	179866	179872	202800	202803	202806	213988	228518
								228519

These changes affect Operation M-661 Piston Rings - Renew All - on the Twelve Cylinder car. The new price is \$18.24. All other models, \$12.16. The 120 and 120-B prices do not change.

Part number 304688 Bearing should be changed from \$7.70 . . . to . . . \$7.00.

Operation A-324 is affected. The new price for material is \$7.11.

CHANGES HAVE ALSO BEEN MADE ON THE FOLLOWING 120 AND 120-B OPERATIONS:--

E-56.....0.3 hrs.	B-623.....0.3 hrs.	M-972.....0.8 hrs.	M-662.....2.5 hrs.
E-53.....0.3 hrs.	A-140.....0.3 hrs.	F-149.....1.2 hrs.	F-130.....2.6 hrs.
B-618.....0.3 hrs.	M-386.....0.3 hrs.	F-110.....1.3 hrs.	F-144.....2.6 hrs.
B-616.....0.3 hrs.	M-33.....0.3 hrs.	F-111.....1.3 hrs.	F-146.....2.6 hrs.
B-619.....0.3 hrs.	B-61.....0.5 hrs.	L-18.....1.5 hrs.	A-410.....3.7 hrs.
B-617.....0.3 hrs.	F-451.....0.5 hrs.	F-137.....1.6 hrs.	M-20.....4.4 hrs.
B-622.....0.3 hrs.	F-148.....0.6 hrs.	F-145.....1.6 hrs.	M-24.....5.5 hrs.
		F-147.....1.6 hrs.	A-153.....0.7 hrs.

NOTE: Operation A-153 is not included in A-10, A-11, A-12, and A-165.

Yours very truly,
PACKARD MOTOR CAR COMPANY

H. C. Taylor.

HCT:F
3(b-x) 2000
Dealers'TL-169

H. C. Taylor
Service Department