REFER TO THIS LETTER BY NUMBER

PACKARD MOTOR CAR COMPANY

DETROIT MICHIGAN

May 25, 1929

To: Packard Distributers

Subject: BONNET SIDE AND DOOR ASSEMBLIES 626-633

TO BE NOTED AND INITIALED BY						
			200		725	
	6					
19					9 70	
-					100	
					100	
				93		

The 640 type bonnet side and door assemblies for model 626-633 open and enclosed bodies which we have been shipping and billing at net \$15.00 each prime and net \$19.50 each painted, will hereafter be shipped when ordered and billed at net \$18.00 each prime, net \$22.50 each painted.

The following part numbers cover these assemblies:

169094	Bonnet side and door assembly—right. Open Cars. Prime—Net \$18.00 Painted—Net \$22.50	626-633
169095	Bonnet side and door assembly—left. Open cars. Prime—Net \$18.00 Painted—Net \$22.50	626-633
169096	Bonnet side and door assembly—right. Closed cars. Prime—Net \$18.00 Painted—Net \$22.50	626-633
169097	Bonnet side and door assembly—left. Closed cars. Prime—Net \$18.00 Painted—Net \$22.50	626-633

To assemble these to the old bonnet, it is only necessary to pull out the old bonnet side hinge pin, remove the standard side and assemble the new side and door assemblies by inserting the hinge pin.

Complete bonnet assemblies with these side and door assemblies should not be ordered as there will be no credit allowance for the old bonnet assemblies. Standard bonnet sides which are removed should not be returned to the factory as no credit allowance will be made.

Very truly yours

(e) 2800

PACKARD MOTOR CAR COMPANY

B. R. Horsley

Manager Service Stores