

PACKARD MOTOR CAR COMPANY

DETROIT MICHIGAN

May 26, 1929

To: Packard Distributors

Subject: RADIATOR REPAIRS

TO BE NOTED AND INITIALED BY	

All radiator core and anchorage assemblies returned to the Factory for repairs should be identified with R. G. Claim tags plainly labelled "Clean, repair and return." Until further notice a flat charge of Three Dollars and Fifty Cents (\$3.50) will be made for this service.

If upon examination the radiator sent in for this work is found to be in such condition as to require a new core, we will notify you immediately.

A re-coring service is now available and if the radiator assembly is complete in every respect with no breaks and bad dents in the tanks or side frames, we will accept it on a "Credit less re-coring" basis and place it in our Service Stock.


The privilege of returning re-cored units that are not suitable for stock is retained and additional charges will be made if parts other than a new core is required.

Please consult this list before making up your claim tags.

Piece No.	Name	Model	Re-Coring Charge
135197	Rad. core & anchorage asb.	226-233-326-333	\$16.00
141513	" " " "	326-333-426-433	16.00
141514	" " " "	326-333-426-433	16.00
145882	" " " "	526-533	16.00
124171	" " " "	136-133-236-233	16.50
141472	" " " "	336-343	16.50
145884	" " " "	443	16.50
158854	" " " "	626-633	16.50
159711	" " " "	640-645	17.00

Yours very truly

PACKARD MOTOR CAR COMPANY



B. R. Horsley
Manager Service Stores

(e) 2800