REFER TO THIS LETTER BY NUMBER

PACKARD MOTOR CAR COMPANY

DETROIT MICHIGAN

October 23, 1929.

To: Packard Distributers and Dealers

Subject: CHANGE IN BRAKE FRONT CAMSHAFT

	11/2/2		T.
		HOU	
No. of the last	14130		
		1	
			- 12

Gentlemen:

The Brake Front Camshaft on models 236-243-336-343-443-326-333-426-433 - 526 - 533 with Bendix type brakes, which were originally $1\frac{\pi}{2}$ in diameter, have been changed to $1\frac{3}{4}$ in diameter.

The factory no longer furnishes the $1\frac{1}{2}$ " Camshaft and this change also necessitates the changing of the bracket. Therefore, when ordering, kindly use the latest part numbers covering the new Brake Front Camshaft and Bracket Assembly.

New details are not interchangeable with corresponding details of old design.

Model	Obsolete Type	New Design Camshaft and Bracket Assembly	Detail Parts of New Assembly
236–243 336–343	139182 97508	97518—Right	97559 Bracket 97555 Pivot 97557 Camshaft R. H. 97553 U. J. Cover
236–243 336–343	139084 97509	97523—Left	97559 Bracket 97555 Pivot 97558 Camshaft L. H. 97553 U. J. Cover
326–333 426–433	139182 97508	97519—Right	97556 Bracket 97555 Pivot 97557 Camshaft R. H. 97553 U. J. Cover
326–333 426–433	139084 97509	97522—Left	97556 Bracket 97555 Pivot 97558 Camshaft L. H. 97553 U. J. Cover

	Obsolete	New Design Camshaft and	Detail Parts of New
Model	Туре	Bracket Assembly	Assembly
443	147470 97510	97520—Left	97561 Bracket L. H. 97555 Pivot 97554 Camshaft L. H. 97553 U. J. Cover
443	147471 97511	97521—Right	97560 Bracket R. H. 97555 Pivot 97550 Camshaft R. H. 97553 U. J. Cover
526–533	147471 97511	97516—Right	97551 Bracket R. H. 97555 Pivot 97550 Camshaft R. H. 97553 U. J. Cover
526–533	147470 97510	97515—Left	97552 Bracket L. H. 97555 Pivot 97554 Camshaft L. H. 97553 U. J. Cover

A similar change was made in the sixth series, but due to the two-way shock absorbing equipment, we had very few complaints and consequently, we are furnishing detail parts for either the $1\frac{1}{2}$ or the $1\frac{3}{4}$ design. These are listed in our Service Parts Lists.

Very truly yours,

PACKARD MOTOR CAR COMPANY.

B. R. HORSLEY,

Manager Service Stores.

HN

(e) 2800