## Technical Letter No.

REFER TO THIS LETTER BY NUMBER TO BE NOTED AND INITIALED BY

## PACKARD MOTOR CAR COMPANY

## DETROIT MICHIGAN

April 4, 1932

TO:

PACKARD DISTRIBUTERS AND DEALERS

SUBJECT: BONNET SIDE AND DOOR ASSEMBLIES

This letter supersedes and cancels Technical Letter 1906.

Door ventilating type bonnet sides, as used on 640, 740 and 840 cars, will be supplied for 626-633, 726-733 and 826-833 cars. These will be shipped either in prime or painted. When painted sides are ordered, complete specifications must be furnished.

Bonnet Side & Door Assembly - Suggested List Prices

	Zone 1	Zone 2	Zone 3
169094 - Right 626-633 Prime	\$18.50	\$19.35	\$21.05
Open. cars Pain	ted 23.10	24.15	26.25
169095 - Left 626-633 Prime	18.50	19.35	21.05
Open cars Paint	ed 23.10	24.15	26.25
169096 - Right 626-633 Prime	18.50	19.35	21.05
Enclosed cars Pain	ted. 23.10	24.15	26.25
169097 - Left 626-633 Prime	18.50	19.35	21.05
Enclosed cars Paint	ted 23.10,	24.15	26.25
178045 - Right 726-733 Prime	18.50	19.35	21.05
Open & Enclosed cars Paint	ted 23.10	24.15	26.25
178046 - Left 726-733 Prime	18.50	19.35	21.05
Open & Enclosed cars Paint	ed. 23.10	24.15	26.25
185194 - Right 826-833 Prime	18.50	19.35	21.05
Open & Enclosed cars Paint	ted 23.10	24.15	25.25
195195 - Left 826-833 Prime	18.50	19.35	21.05
Open & Enclosed cars Pain	ted 23.10	24.15	26.25

Complete bonnet assemblies should not be ordered as the installation of bonnet sides is very simple. No credit will be allowed on old bonnets, or on old bonnet sides.

> Yours very truly, PACKARD MOTOR CAR COMPANY

Service Department

(e) 2800

PRICES QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE