

Burk

PACKARD MOTOR CAR COMPANY

DETROIT MICHIGAN

REFER TO THIS LETTER BY NUMBER

| TO BE NOTED AND INITIALED BY | |
|------------------------------|--|
| | |
| | |
| | |
| | |
| | |
| | |

November 5, 1930

To PACKARD DISTRIBUTERS AND DEALERS

Subject BONNET SIDE AND DOOR ASSEMBLIES

Gentlemen:

This letter supersedes and cancels Technical Letter 1887 and all previous letters on this subject.

The door ventilating type of bonnet sides of the design as used on models 640, 740 and 840 can be supplied for models 626-633, 726-733 and 826-833. These will be supplied in prime or painted, but when painted sides are ordered, complete specifications must be furnished.

The following part numbers cover these assemblies:

| | | | <u>Suggested List Prices</u> | | |
|--------|---|---------|------------------------------|---------------|---------------|
| | | | <u>Zone 1</u> | <u>Zone 2</u> | <u>Zone 3</u> |
| 169094 | Bonnet Side & Door Assembly right 626-633 | Prime | \$16.85 | \$17.65 | \$19.55 |
| | Open cars | Painted | 21.00 | 22.00 | 24.40 |
| 169095 | Bonnet Side & Door Assembly left 626-633 | Prime | 16.85 | 17.65 | 19.55 |
| | Open cars | Painted | 21.00 | 22.00 | 24.40 |
| 169096 | Bonnet Side & Door Assembly right 626-633 | Prime | 16.85 | 17.65 | 19.55 |
| | Enclosed cars | Painted | 21.00 | 22.00 | 24.40 |
| 169097 | Bonnet Side & Door Assembly left 626-633 | Prime | 16.85 | 17.65 | 19.55 |
| | Enclosed cars | Painted | 21.00 | 22.00 | 24.40 |
| 178045 | Bonnet Side & Door Assembly right 726-733 | Prime | 16.85 | 17.65 | 19.55 |
| | Open and Enclosed cars | Painted | 21.00 | 22.00 | 24.40 |
| 178046 | Bonnet Side & Door Assembly left 726-733 | Prime | 16.85 | 17.65 | 19.55 |
| | Open and Enclosed cars | Painted | 21.00 | 22.00 | 24.40 |
| 185194 | Bonnet Side & Door Assembly right 826-833 | Prime | 16.85 | 17.65 | 19.55 |
| | Open and Enclosed cars | Painted | 21.00 | 22.00 | 24.40 |
| 185195 | Bonnet Side & Door Assembly left 826-833 | Prime | 16.85 | 17.65 | 19.55 |
| | Open and Enclosed cars | Painted | 21.00 | 22.00 | 24.40 |

Any references herein, to future business, are made subject to the continuance of the existing agreement between the Manufacturer and the Distributer

PACKARD MOTOR CAR COMPANY

To assemble these to the old bonnet, it is necessary only to pull out the old bonnet side hinge pin, remove the standard side and assemble the new side and door assemblies by inserting the hinge pin.

Complete bonnet assemblies with these side and door assemblies should not be ordered as there will be no credit allowance for the old bonnet assemblies. Standard bonnet sides which are removed should not be returned to the factory as no credit allowance will be made.

Kindly disregard the suggested list prices on piece numbers 178045 and 178046 as shown in Service Parts Price List #21 and use the suggested prices quoted in this letter, also please change your price list accordingly.

Yours very truly,

PACKARD MOTOR CAR COMPANY

B. R. Horsley

B. R. Horsley
Manager Service Stores

BRH:HN
(e) 2800