

bulletin



51GS-44 Dealer 36 December 14, 1951

To: ZONES AND DEALERS

Subject: PA-422706 ELECTRICAL ANTENNAS

There have been a certain number of PA-422706 Electrical Antennas, as used on 24th and 25th Series cars, returned by dealers as being defective within the warranty period. In many instances the details, such as the lead-in, operating switch, miscellaneous hardware, etc., are not returned, thereby not only making the assembly extremely difficult to check for defects but also necessitating the fabrication of new details to make the assembly complete.

Therefore, effective January 2, 1952, all PA-422706 Electrical Antennas returned by dealers must include all detail parts or the unit will be returned to the dealer transportation collect and no credit consideration will be given.

It is necessary to make this decision due to the shortage of basic materials and in the interests of national defense efforts.

Very truly yours,

J. A. Carr, Manager

Parts and Service Department

JAC/cra