

SPECIAL "SELL MORE PARTS" BULLETIN

PACKARD PARTS for PACKARD CARS

PACKARD SERVICE for PACKARD OWNERS



SERVICE STORES DIVISION

PACKARD MOTOR CAR COMPANY

DETROIT, MICH.

PACKARD DISTRIBUTERS AND DEALERS

NO. 135

ATTENTION OF General Manager, Service Manager
and Stores Manager

DATE July 13, 1934

Special prices have been assigned to a wide selection of new windshield assemblies on which we have accumulated considerable overstock. Our sales opportunities can be best understood when we point out that for very little more than the cost of the installation of a new windshield glass a bright new complete windshield assembly can be obtained. These units normally sell for around \$90 and you will agree these are remarkable values. Service men, however, should be entirely familiar with any local, state or national regulations with regard to glass replacements.

COMPLETE WINDSHIELD ASSEMBLIES

No.	Type	Finish	Models	Bodies	Glass	Suggested List Price
164659	1 Pc	Chrome	633-40	Tour	Plate	\$18.18
164657	"	"	" "	Rdstr-Phae	"	18.18
164665	"	"	626-33-40	Conv.Coupe	"	18.18
148692	"	B.E.	443	Cust.Sedan	"	18.18
139972	"	B.E.	326-33-236-43	Coupe, Sed., Limo.	"	18.18
145045	"	N.P.	533,443	Tour	"	18.18
143153	"	Walnut	" "	"	"	18.18
138233	"	"	326-36-426	Rdstr-Phae	"	18.18
138234	"	B.E.	333,443	Tour	"	18.18
173840	"	C.P.	733-40-45, 833-40	Tour	Safety	18.18
164921	Folding	"	633-40	Tour	Plate	35.35
165401	1 Pc	"	645	Open	Safety	35.35

All prices quoted are "Special Close-out" prices and are established to liquidate excess stock. Your parts discount is indicated by the letter preceding the piece number. Dealers, when ordering items offered at special prices will be required to indicate the suggested list price, the bulletin number and date of issue.

Yours very truly,
PACKARD MOTOR CAR COMPANY

B. R. Horsley
Manager Service Stores Division

F:AW
(50)