

SPECIAL "SELL MORE PARTS" BULLETIN

PACKARD PARTS for PACKARD CARS

PACKARD SERVICE for PACKARD OWNERS

SERVICE STORES DIVISION



PACKARD MOTOR CAR COMPANY

DETROIT, MICH.

PACKARD DISTRIBUTERS AND DEALERS

NO. 138

ATTENTION OF
General Manager
Service Manager
Stores Manager

DATE Aug. 1, 1934

These are 634 and 734 speedster parts. There is a very limited number of these models in service, therefore, the special prices assigned have been made extremely attractive. Notify the owners of Packard speedsters that these items are available at greatly reduced figures. Service men should be prepared to inform prospective purchasers the results that may be expected if any of these parts are installed in other than the models for which they were designed.

<u>Part No.</u>	<u>Name</u>	<u>Model</u>	<u>Suggested List Price</u>
70021	Motor camshaft	734	\$13.64
7056	Motor camshaft	634	13.64
7636	Cyl. head (6.00 to 1)	634	10.95
9573	Cyl. head H.C. (After motor 184042)	734	10.95
9572	Cyl. head (After motor 184042)	734	10.95
8032	Carburetor Asb. (For H.C. head)	734	18.18
9852	Carburetor Asb. (For L.C. head)	734	18.18
40196	Gear & pinion assembly (3.31 to 1)	634-734	17.35
4766	Diff. case assembly	634-734	9.09
8241	Exhaust pipe assembly	734	9.09
8206	Radiator assembly	734	18.18

All prices quoted are "Special Close-Out Prices" and are established to liquidate surplus stock. Your parts discount is indicated by the letter following the piece number.

Dealers, when ordering items offered at special prices, will be requested to show the suggested list price, the bulletin number and date of issue.

Yours very truly,
PACKARD MOTOR CAR COMPANY

B. R. Horsley
Manager Service Stores Division

AW