
Packard,

TECHNICAL SERVICE BULLETIN



Dealer 47T-15 June 26, 1947

To: REGIONS, ZONES, AND DEALERS

Subject: ALTERNATE INSTRUMENT PANEL LIGHT SWITCHES

Cars are now being shipped with an alternate instrument panel light switch in which the contact arrangement differs from the standard switch. The use of these switches is only a temporary measure and the standard switches will again be used as soon as they are available.

With this alternate switch the instrument panel lights are off when the switch knob is in against the panel and on "bright" when the knob is pulled out to the first position. Pulling the switch knob out to the second and third positions provides two degrees of dimming.

The alternate switch does not have provisions for mounting the tail lamp circuit fuse. When this switch is used the fuse is located in a fuse container in the cable from the headlight switch to the instrument light switch.

Very truly yours

Theo. P. Thomas

Service Technical Manager

TPT: CMK