

Packard **SERVICE TECHNICAL** **Bulletin**

Dealer 48T-21
August 30, 1948

To: REGIONS, ZONES AND DEALERS

Subject: SEVEN-QUART CRANKCASE CAPACITY - 22ND SERIES EIGHT
AND SUPER EIGHT


A new and larger oil pan is now being used in production on Eight and Super Eight engines. These late engines may be identified by the suffix letter "D" after the engine number.

Purchasers of cars with these late "D" engines should be told the crankcase capacity is seven quarts as stated on the Owner's Manual Envelope and not six quarts as shown on page 41 of the book.

The larger oil pan assembly and the affected replacement parts are carried under the following part numbers:

- 412640 Oil Pan Assembly
- 412643 Oil Strainer Bearing and Bracket Assembly
- 412642 Oil Strainer Bracket
- 412641 Oil Strainer Suction Tube
- 412644 Oil Level Indicator Assembly

Very truly yours,



N. A. Lull
Service Technical Manager

NAL:ps