

Packard **SERVICE TECHNICAL**
Bulletin

Dealer 48T-29
November 8, 1948

To: REGIONS, ZONES AND DEALERS

Subject: CORRECTIONS IN 1948 FLAT RATE MANUAL

The 1948 Flat Rate Manual lists Operation F-3 and F-25 with the same time allowance. This is incorrect and should be changed.

Operation F-3 should read as follows:

F-3 Radiator Core and Cooling System - Power Flush
Includes: Replace all necessary hose and
change thermostat.

2201-02-06-13-22-26-40

1.7 hrs.

Operation F-25 should remain unchanged.

Please make this change in your 1948 Flat Rate Manual.

Very truly yours,



N. A. Lull
Service Technical Manager

NAL:ps