



# Packard SERVICE TECHNICAL bulletin

Dealer 48T-3

January 28, 1948

To: REGIONS, ZONES AND DEALERS

Subject: NEW SHOP MANUAL, SECOND SECTION

The Second Section of the Packard Shop Manual for 1948 is now available and a sample copy is attached. This section covers the reconditioning of the rear axle.

You will notice the more convenient size of the Shop Manual and each section will follow the same size and style. Other sections will follow as promptly as they can be released.

The number of copies received by Zones and Dealers is determined by the number of bulletins received by each. Additional copies of the manuals may be obtained through Zone Offices at 25¢ per copy for each section. This charge is nominal and in no way covers the cost of preparation and printing but has been established as a means of control over the distribution of Shop Manuals.

Very truly yours,



N. A. Lull  
Service Technical Manager

NAL:ps

Encl.