



**Packard** **SERVICE** **TECHNICAL**  
**Bulletin**

49T-36, Dealer 28

December 8, 1949

To: ZONES AND DEALERS

Subject: REPLACEMENT ULTRAMATIC DRIVE UNITS

The Factory Parts Warehouse now is shipping service replacement Ultramatic Drive units for the 2301 models (Eight and Deluxe Eight).


Units for the 2301 models may be identified by the six-digit unit number stamped on the rear end at the left side of the case. Units for Super Eight and Custom Eight carry a three, four, or five digit unit number.

The two units differ in internal construction in that the units for the 2301 models contains 10 high range clutch plates whereas the unit for the other models contains 12 plates. One unit should not be used to replace the other when it is necessary to replace a complete assembly.

Replacement units should be ordered under the part numbers listed below.

902382 Ultramatic Drive Transmission Assembly - 2301  
902380 Ultramatic Drive Transmission Assembly - 2302-06-32-33

Very truly yours,



J. A. Carr, Manager  
Parts and Service Department