

Packard **SERVICE TECHNICAL**
Bulletin

The logo features a large, stylized red letter 'P' on the left. Inside the 'P', there are white line drawings of a wrench, a pair of pliers, and a screwdriver. A red arrow points from the right side of the 'P' towards the word 'Bulletin'.

50T-56, Dealer 43
December 8, 1950


To: ZONES AND DEALERS

Subject: FROZEN DOOR LOCKS - 24TH SERIES

Water in the door handle push button mechanisms and lock cylinders often results in frozen door locks and buttons when the temperature drops below the freezing point.

Applying 10-W or 3-IN-1 oil into the key openings and between the push button and button opening in the handles will reduce the possibility of this condition occurring. Before applying the oil, the lock cylinder and the push button opening should be dried out with compressed air.

Yours very truly,

A handwritten signature in blue ink that reads 'J. A. Carr'.

J. A. Carr, Manager
Parts and Service Department

JAC:ljk