

10



Packard SERVICE TECHNICAL Bulletin

52T-38

December 3, 1952

TO: ZONES

SUBJECT: RADIATOR CORE UPPER TANK - 24th and 25th SERIES

Due to Government restrictions, the use of copper in radiator cores was curtailed during part of the 24th Series production; therefore, some of the radiators were built with steel upper tanks.

In some instances it has been necessary to replace a radiator core assembly just because the upper tank was leaking and could not be repaired. A replacement radiator core upper tank is now available for the 24th and 25th Series cars as a service item and may be ordered under Part Number 436605.

It is recommended that now, more than ever, radiators should be kept clean, and that Packard Rust Preventive be added at least twice a year.

Very truly yours,



J. A. Carr
General Service Manager

JAC:kb