



Packard

SERVICE

TECHNICAL

Bulletin

14

52T-42

December 31, 1952

TO: ZONES

Subject: 1952 PACKARD SERVICE TECHNICAL BULLETIN INDEX

52T-1	Dlr. 1	Jan. 28, 1952	Pump Check Valve Noise, Ultramatic
52T-2	Dlr. 2	Jan. 29, 1952	Water in Overdrive Governors
52T-3	Dlr. 3	Jan. 29, 1952	Rear Stabilizer Arm Bolts - 24th and 25th Series
52T-4	Dlr. 4	Jan. 29, 1952	Gasoline Gum
52T-5	-	Jan. 30, 1952	Changes in Ultramatic (Confidential)
52T-6	Dlr. 5	Jan. 31, 1952	Ultramatic Driving Operation Under Emergency Conditions
52T-7	Dlr. 6	Jan. 31, 1952	Rear Axle Floor Bumper - 24th Series
52T-8	-	Feb. 5, 1952	Water Leaks
52T-9	Dlr. 7	Feb. 6, 1952	Upper Support Arm Inner Bracket Bolts - 24th and 25th Series
52T-10	-	Feb. 7, 1952	Ultramatic Drive Converter Whine or Whistle - 25th Series Cars
52T-11	-	Feb. 13, 1952	Upper Support Arm Inner Bracket Bolts - 24th and 25th Series
52T-12	Dlr. 8	Feb. 18, 1952	Door Locking Rod and Knobs - 25th Series
52T-13	Dlr. 9	Mar. 25, 1952	Easamatic Vacuum Piston Stop
52T-14	Dlr. 10	Mar. 31, 1952	Ultramatic Drive Operation - "Coasting"
52T-15	Dlr. 11	Mar. 31, 1952	Easamatic Power Brake Kit - Installation Time
52T-16	Dlr. 12	Apr. 4, 1952	Easamatic Operation - Hard Pedal
52T-17	-	May 28, 1952	1952 Service Technical Bulletin Index - Jan. thru April
52T-18	Dlr. 13	May 28, 1952	1952 Service Technical Bulletin Index - Jan. thru April
52T-19	-	May 22, 1952	Ultramatic Drive Oil Cooler - 23rd Series
52T-20	-	Jun. 2, 1952	Direct Drive Clutch Plate - Ultramatic 11 $\frac{1}{4}$ " Diameter
52T-21	Dlr. 14	Jun. 12, 1952	Ultramatic High Range Clutch Plates - Replacement
52T-22	Dlr. 15	Jun. 23, 1952	Back Up Light Switch Bracket Rubbing Rear Brake Tube
52T-23	Dlr. 16	Jun. 23, 1952	Body Panel Striking Frame
52T-24	Dlr. 17	Jun. 30, 1952	Rear Universal Joint Removal - Ultramatic Equipped Cars
52T-25	Dlr. 18	Jul. 2, 1952	Easamatic, Repair Kits and Warranty
52T-26	Dlr. 19	Jul. 2, 1952	Front Universal Joint Lubrication
52T-27	Dlr. 20	Jul. 15, 1952	Noisy Shock Absorbers
52T-28	Dlr. 21	Aug. 13, 1952	Thermostats and Overheating
52T-29	Dlr. 22	Sep. 16, 1952	Removing Clocks

(over)

52T-30 - Sep. 19, 1952 Changes in Ultramatic (Confidential)  
 52T-31 Dlr. 23 Oct. 3, 1952 Starter Bendix Noise - 25th Series  
 52T-32 - Oct. 17, 1952 Noisy Differentials  
 52T-33 Dlr. 24 Nov. 20, 1952 Disturbance in Reverse - Ultramatic 25th Series  
 52T-34 Dlr. 25 Dec. 2, 1952 Power Steering - 25th and 26th Series  
 52T-35 Not issued - See Airgram from J. A. Carr dated January 28, 1953  
 52T-36 Dlr. 26 Nov. 25, 1952 26th Series Rear Axle  
 52T-37 Dlr. 27 Dec. 31, 1952 Campaign - 4-Barrel "WCFB"  
 52T-38 - Dec. 3, 1952 Radiator Core Upper Tank - 24th and 25th Series  
 52T-39 Dlr. 28 Dec. 18, 1952 Windshield Defroster Opening - 26th Series  
 52T-40 Dlr. 29 Dec. 23, 1952 Door Water Leaks, 26th Series - 2 and 4-Door  
 Sedans  
 52T-41 Dlr. 30 Dec. 30, 1952 Rear Axle Pinion Bearing Preload, 26th Series

Very truly yours,

*J. A. Carr*  
 J. A. Carr,  
 General Service Manager

JAC:bjm