



Packard SERVICE TECHNICAL Bulletin

55T-56
December 31, 1955

To: ZONES

Subject: INDEX - SERVICE TECHNICAL BULLETINS - JANUARY 1, 1955 THROUGH
DECEMBER 31, 1955

<u>Subject</u>	<u>Zone</u>	<u>Dlr.</u>	<u>Date</u>
AIR CONDITIONING			
Air Conditioning Service Kit - 55th Series	55T-45	36	Nov. 4, 1955
BODY			
Front Underseat Heater Fan Guard - 54th Series	55T-9	8	Feb. 3, 1955
Instrument Panel Paint Schemes - 55th Series	55T-21	18	May 25, 1955
Rear Cigar Lighters - 5582-87	55T-14	12	Mar. 10, 1955
Rear Window Outside Trim Plates - 56th Series	55T-51	42	Dec. 2, 1955
Stained Headlining - 55th Series Clippers	55T-30	21	June 28, 1955
Stained Headlining - 55th Series Clippers - Correction	55T-44	35	Oct. 20, 1955
Windshield Weatherstrip and Moulding Retainers - 55th Series	55T-10	9	Feb. 10, 1955
Windshield Weatherstrip Retainer - Revised - 55th Series	55T-34	25	July 15, 1955
BRAKES			
Easamatic Power Brake - Hard Pedal - 55th Series	55T-28	-	June 15, 1955
CARBURETOR			
AC Carburetor Air Cleaner - 5540	55T-24	19	June 6, 1955
Gasoline Fumes - 5560-80	55T-41	32	Sep. 14, 1955
ELECTRICAL			
Battery - Negative Terminal Grounded - 56th Series	55T-49	40	Nov. 17, 1955
Ignition Cable Support Bracket - 5588 Relocated	55T-25	-	June 6, 1955
Rear Cigar Lighters - 5582-87	55T-14	12	Mar. 10, 1955
Storage Battery - Replacement	55T-15	13	Mar. 28, 1955
12-Volt Battery Characteristics	55T-3	3	Jan. 19, 1955